

**AMENDMENTS TO THE DRAWINGS:**

The enclosed Figure 6 replaces original Figure 6, in which the location of the fault "X" has been repositioned and the fault has been marked with reference numeral 480. The fault "X" has been repositioned between main breaker 415 and feeder breakers 420, 425. These amendments merely conform the drawing with the specification as seen in paragraph [0066]. No new matter is added.